



Work Order (Bid Form)

WORK ORDER INFORMATION

Work Order Name: WO/10001BL0501/1

Work Order Type: Weatherization

Audit Name: 10001BL0501

CLIENT INFORMATION

Client Name:

Address:

Client ID: 10001BL0501

, 37701

Alt. Client ID: BLOUNT

AGENCY INFORMATION

Agency: Blount County Community Action Agency

Agency Phone: (865) 983-8411

Address: 3509 Tuckalee Pike
Maryville, TN 37803

Fax: (865) 681-1781

Email Address:

Agency Contact: Larson, Bruce

Work Phone: (865) 310-7333

Cell Phone: (865) 310-7333

Email Address: brujanie@charter.net

Company Name & License Number: _____

Contractor's Signature: _____

COMMENT

Auditor: Bruce Larson

(865-310-7333)

Audit conducted on 3/29/12 & 4/5/2012

Site Built: 1920's

Client Name:

Client ID: 10001BL0501

Alt. Client ID: BLOUNT

Work Order (Bid Form)

Work Order Name: WO/10001BL0501/1

Report Run On: 4/9/2012

DOE Weatherization Assistant

Version 8.6.0

Page 1 of 7

Measures

Measure 1 Frame in and install Hollow Core Interior door at bottom of stairway.

Components

Inspected

Comment Client is losing a large amount of heat/air with this opening. Client does not use upstairs very often, but is having to heat/cool it. Recommend, Framing in and installing Hollow Core interior door at bottom of stairway. Non locking Left Hand swing. White.

Stairwell opening Size: Approx. 36" X 96 "

☐

#	Material / Labor	Description / Comment	Units	Estimated			Actual		
				Qty	Unit Cost	Total	Qty	Unit Cost	Total
10	Unspecified	Misc Material	Each	1					

Other Detail

<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>
<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>

Measure Sub Total:

Sub Total:

Field Notes:

Measure 2 Wrap Approx. 40' of Metal Duct Work with Silver Faced Duct Wrap. (1- 1/2")

Components

Inspected

Comment Wrap Approx 40 feet of Metal Duct Work with Silver Faced Duct Wrap. (1 1/2" size) In basement.

☐

#	Material / Labor	Description / Comment	Units	Estimated			Actual		
				Qty	Unit Cost	Total	Qty	Unit Cost	Total
10	Unspecified	Silver faced Duct Wrap.	Each	1					

Other Detail

<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>
<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>

Measure Sub Total:

Sub Total:

Field Notes:

Client Name:

Client ID: 10001BL0501

Alt. Client ID: BLOUNT

Work Order (Bid Form)

Work Order Name: WO/10001BL0501/1

Report Run On: 4/9/2012

DOE Weatherization Assistant

Version 8.6.0

Page 2 of 7

Measure 3 Infiltration Redctn**Components****Inspected****Comment**☐

1. Weather Strip interior door to basement. (30" x 71")
2. Weather Strip DR 3 (32" x 80 ")
3. Foam drainlines and backside of cabinet under kitchen sink . Area to seal is approx. 2" x 12" .
4. Foam drain lines in upstairs bath
5. Weather Strip closet door to Finished attic in upstairs bedroom (30" x 77 ") .
Add 30" threshold.

#	Material / Labor	Description / Comment	Units	Estimated			Actual		
				Qty	Unit Cost	Total	Qty	Unit Cost	Total
10	Miscellaneous Su	Infiltration Reduction	Each	1	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>
Other Detail									
	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>
	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>
Measure Sub Total:						<input type="text"/>	Sub Total:		<input type="text"/>

Field Notes:**Measure 4 DWH Tank Insulation****Components****Inspected****Comment** 40 Gallon Natural Gas☐

#	Material / Labor	Description / Comment	Units	Estimated			Actual		
				Qty	Unit Cost	Total	Qty	Unit Cost	Total
1	Hot Water Equipm	DHW Tank Insulation	Each	1	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>
2	Labor	DHW Tank Insulation	Each	1	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>
Other Detail									
<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>
<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>
Measure Sub Total:						<input type="text"/>	Sub Total:		<input type="text"/>

Field Notes:

Client Name:

Client ID: 10001BL0501

Alt. Client ID: BLOUNT

Work Order (Bid Form)

Work Order Name: WO/10001BL0501/1

Report Run On: 4/9/2012

DOE Weatherization Assistant

Version 8.6.0

Page 3 of 7

Measure 5 DWH Pipe Insulation**Components****Inspected****Comment**☐

Insulate 6' water pipes (each) Hot/Cold

Pipes have some insulation. Needs to be removed and rewrapped. Not properly wrapped.

#	Material / Labor	Description / Comment	Units	Qty	Estimated		Actual		
					Unit Cost	Total	Qty	Unit Cost	Total
1	Insulation	DHW Pipe Insulation	Each	1	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>
2	Labor	DHW Pipe Insulation	Each	1	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>

Other Detail

<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>
<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>

Measure Sub Total:**Sub Total:****Field Notes:**

Client Name:

Client ID: 10001BL0501

Alt. Client ID: BLOUNT

Work Order (Bid Form)

Work Order Name: WO/10001BL0501/1

Report Run On: 4/9/2012

DOE Weatherization Assistant

Version 8.6.0

Page 4 of 7

Measure 6 Floor Ins. R-19**Components** FD1**Inspected**

Comment Approx. (75) sq. ft. of old fiber board will need to be removed prior to installing insulation. Reason for additional cost. Install 572 Sq. ft. R- 19 Fiberglass Batts. FD 1

☐

#	Material / Labor	Description / Comment	Units	Qty	Estimated		Actual		
					Unit Cost	Total	Qty	Unit Cost	Total
1	Insulation	Floor Insulation - Fiberglass Faced Batt - R-19	SqFt	572	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>
2	Labor	Floor Insulation - Fiberglass Faced Batt - R-19	SqFt	572	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>
3	Miscellaneous Su	Added Misc Cost (Removal of old fiber board.	Each	1	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>

Other Detail

<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>
<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>

Measure Sub Total:**Sub Total:****Field Notes:**

Client Name:

Client ID: 10001BL0501

Alt. Client ID: BLOUNT

Work Order (Bid Form)

Work Order Name: WO/10001BL0501/1

Report Run On: 4/9/2012

DOE Weatherization Assistant

Version 8.6.0

Page 5 of 7

Measure 7 Floor Ins. R-19**Components** FD3**Inspected**

Comment Contractor will need to remove approx. 133 sq. ft. of old silver faced duct wrap that is stapled to ceiling floor and discard. Reason for additional cost

☐

FD3

Install approx. 133 sq. ft. R-19 Fiberglass Batts.

#	Material / Labor	Description / Comment	Units	Qty	Estimated		Actual		
					Unit Cost	Total	Qty	Unit Cost	Total
1	Insulation	Floor Insulation - Fiberglass Faced Batt - R-19	SqFt	133	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>
2	Labor	Floor Insulation - Fiberglass Faced Batt - R-19	SqFt	133	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>
3	Miscellaneous Su	Added Misc Cost (Removal of old duct wrap stapled to ceiling floor	Each	1	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>

Other Detail

<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>
<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>

Measure Sub Total:**Sub Total:****Field Notes:**

Client Name:

Client ID: 10001BL0501

Alt. Client ID: BLOUNT

Work Order (Bid Form)

Work Order Name: WO/10001BL0501/1

Report Run On: 4/9/2012

DOE Weatherization Assistant

Version 8.6.0

Page 6 of 7

Measure 8 Attic Ins. R-30**Components** AT1**Inspected**

Comment Access to unfinished attic is inside closet upstairs bedroom, in kneewall.
However, contractor will need to blow any allowed insulation from outside house thru (EW 2) Or (WW 2) Gable. Bring to R-38

☐

#	Material / Labor	Description / Comment	Units	Qty	Estimated		Actual		
					Unit Cost	Total	Qty	Unit Cost	Total
1	Insulation	Attic Insulation - Cellulose, Blown - R-30	SqFt	690	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>
2	Labor	Attic Insulation - Cellulose, Blown - R-30	SqFt	690	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>

Other Detail

<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>
<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>

Measure Sub Total: **Sub Total:** **Field Notes:****Measure 9 PressureRelief Piping Needed****Components****Inspected**

Comment Install approx. 40" Pressure Relief Piping

☐

#	Material / Labor	Description / Comment	Units	Qty	Estimated		Actual		
					Unit Cost	Total	Qty	Unit Cost	Total
10	Unspecified	Pressure relief piping (+)	Each	1	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>

Other Detail

<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>
<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>

Measure Sub Total: **Sub Total:** **Field Notes:****Work Order Grand Total:** **Grand Total:**

Client Name:

Client ID: 10001BL0501

Alt. Client ID: BLOUNT

Work Order (Bid Form)

Work Order Name: WO/10001BL0501/1

Report Run On: 4/9/2012

DOE Weatherization Assistant

Version 8.6.0

Page 7 of 7